




## 2008 Race Tip # 11 – Piston Installation

Some of the pistons P/N 2203611 may be incorrectly marked. The arrow on top of the piston may be pointing in the wrong direction.



To insure the piston is installed correctly, make sure the ring locating pin is on the intake side.



***If the piston is installed incorrectly immediate engine damage will occur.***