



POLARIS[®]
Racing



RACE TIP #6

Chain Tensioner Bolt Bending

We have seen instances of the chain tensioner bolt P/N 7517227 bending slightly. The resistance felt from a bent bolt may feel like tension on the chain. Check the condition of the adjuster bolt, replace if necessary. Adjust chain tension as per the instructions on page 6.9 of the 2006 high performance manual.