



POLARIS[®]
Racing



Race Tip # 7 - 2006 440 IQ & Rolling Chassis - New Drive Belt Available

If you are experiencing excessive drive belt failures, a new drive belt **P/N 3211114** is now available through Polaris Racing Parts Support. Call Brad Seavers 715-355-3008.

If you elect to use this belt it is very important that you do not scuff the belt with any kind of abrasive or clean the belt with acetone or solvents. It is critical that you break the belt in for a minimum of one tank of fuel prior to racing. A higher rate driven clutch spring will be required to achieve the correct shift RPM. We recommend using driven clutch spring P/N 7043252 160/280 or P/N 7043255 160/300. These are also available through Polaris Racing Parts Support.