

Tip # 4 – 2007 440 IQ and Roller Front Track Shock Boot Installation.

The front track shock boot may have be installed incorrectly. Check the installation and correct if necessary.

## Front Track Shock



**As installed on some sleds**

**Corrected Installation**