



## **2008 Race Tip # 9 – Drive Clutch Taper**

The clutch taper on the 2008 IQ Racer has a larger diameter (31mm) than in previous years. Installing the smaller diameter clutch taper (29mm) will cause clutch misalignment and can result in crankshaft damage.

# Drive Clutch Changes

MY 07 – Small Taper

MY 08 – Large Taper



Do not install small taper clutch on large taper PTO!!