



POLARIS[®]
The Way Out.

RACING TIP #4

November, 2004

2005 440 IQ and Rolling Chassis Fuel Cap

There is interference with console and the fuel filler cap that can cause the fuel cap to come off. Remove the console from the vehicle. Use a utility knife or die grinder to remove 1/2" from the console in front of the fuel tank filler neck and 1/4" from the console behind the fuel tank filler neck.

