



The limiter straps on the front torque arm of the rear suspension should be moved to upper hole position on the limiter straps. This adjustment will shorten the limiter straps.

